

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

505553

COUNTY Huron TOWNSHIP New London SECTION OF TOWNSHIP 4
OWNER Flora Miller ADDRESS RD New London Ohio
LOCATION OF PROPERTY 1/2 Mi E of Rt 60 on Fayette Rd #42 N side

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)


Casing diameter 4 1/4 Length of casing 130'
Type of screen 1 Length of screen —
Type of pump Sub
Capacity of pump 5 gpm @ 100'
Depth of pump setting 120'
Date of completion —
Test rate 10 gpm Duration of test 6 hrs
Drawdown 90 ft Date Oct - 28
Static level (depth to water) 18 1/2' ft
Quality (clear, cloudy, taste, odor) Slight Sulfur
Pump installed by Driller

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Yellow Clay</u>	<u>0 ft</u>	<u>30 ft</u>
<u>Blue gray Clay</u>	<u>30</u>	<u>100</u>
<u>Broken up Sandstone</u>	<u>100</u>	<u>130</u>
<u>gray shale</u>	<u>130</u>	<u>—</u>

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM Myrl K. Fife
ADDRESS RR1 Greenwich O 44837

DATE Nov 10 1979
SIGNED Myrl K. Fife

*If additional space is needed to complete well log, use next consecutive numbered form.