

ORIGINAL

56

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

505937

COUNTY Vinton TOWNSHIP JACKSON SECTION OF TOWNSHIP 24
OWNER Andy BROADSTONE ADDRESS R.D. #1 McARTHUR, OHIO
LOCATION OF PROPERTY 4 1/2 miles Northwest of SR 93 on Vin. Co. Rd. # 23.

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 12 gpm Duration of test 4 hrs
Drawdown 260.0' ft Date 9-6-77
Static level (depth to water) 250.0' ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by ELLIS & MORRIS DRILLING CO., INC.

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

D Well Rd.

.3 mi. S, SE of T13
on C23, N side
≈ .25 mi. backdrive

Co. Rd. #23

SR 93

1/4 mile

MARTIN

DATE 1-7-78
SIGNED Lewis H. Morris

*If additional space is needed to complete well log, use next consecutive numbered form.

24