

WELL LOG AND DRILLING REPORT

221

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

506410

COUNTY Fairfield TOWNSHIP Pleasant SECTION OF TOWNSHIP 30

OWNER James Perky ADDRESS Stringtown Rd.

LOCATION OF PROPERTY 1 mile south of Rainbow Rd. on Stringtown Rd.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 Length of casing 85

Test rate 21 gpm Duration of test 2 hrs

Type of screen - Length of screen -

Drawdown 20 ft Date 4-21-79

Type of pump Sub.

Static level (depth to water) 52 ft

Capacity of pump 10 G.P.M.

Quality (clear, cloudy, taste, odor) CLEAR

Depth of pump setting 80

Date of completion 4-21-79

Pump installed by John Cone

WELL LOG*

SKETCH SHOWING LOCATION


Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Clay	0 ft	14 ft
Sand	14	23
Gravel	23	47
Sand	47	78
Sand & Gravel	78	85



DRILLING FIRM

John Cone w/ol

DATE

4-23-79

ADDRESS

Day, Ohio 43130

SIGNED

John Cone

*If additional space is needed to complete well log, use next consecutive numbered form.

1977