

WELL LOG AND DRILLING REPORT

ORIGINAL

2 ✓

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBINGState of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

507219

COUNTY DARKE TOWNSHIP LIBERTY SECTION OF TOWNSHIP 33
OWNER William A. LAUX ADDRESS 942 Godfrey Rd. Hollmansburg
LOCATION OF PROPERTY 2nd House on North Side of Godfrey Rd - 1 1/2 mi

CONSTRUCTION DETAILS

EAST OF GLEN PARK

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 4 1/4" Length of casing 137
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____
Test rate 18 gpm Duration of test 3 hrs
Drawdown 3 ft Date 8-7-80
Static level (depth to water) 57' ft
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION


Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

<u>YELLOW CLAY</u>	0 ft	<u>22</u> ft
<u>Hard Pan</u>	<u>22</u>	<u>61</u>
<u>Dry GRAVEL</u>	<u>61</u>	<u>64</u>
<u>Hard Pan</u>	<u>64</u>	<u>135</u>
<u>limestone</u>	<u>135</u>	<u>156</u>



DRILLING FIRM

ADDRESS

DATE

SIGNED

Ralph Capprock
Hollmansburg, Pa.

8-4-80Ralph Capprock

*If additional space is needed to complete well log, use next consecutive numbered form.

64