

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

507220

21 ✓

COUNTY DARKE TOWNSHIP NEAVE SECTION OF TOWNSHIP 29
OWNER MELISE SAYLOR ADDRESS 3717 SHIRA Rd. GREENVILLE, O.
LOCATION OF PROPERTY 3rd HOUSE SOUTH ON EAST SIDE OF SHIRA Rd. IN WEAVER STATION

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 4 1/4" Length of casing 26 Test rate 18 gpm Duration of test 3 hrs
Type of screen _____ Length of screen _____ Drawdown 10' ft Date 11-14-80
Type of pump _____ Static level (depth to water) 14 ft
Capacity of pump _____ Quality (clear, cloudy, taste, odor) CLEAR
Depth of pump setting _____ Pump installed by _____
Date of completion _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

CLAY

0 ft

11 ft

HARD PAN

11

23

LIMESTONE

23

46

W

N

WEAVER STATION - FT. JEFFERSON Rd.

SHIRA Rd.

□ WELL

H. Wind Rd.

E

S

DRILLING FIRM

ADDRESS

DATE

SIGNED

Ralph Cappock
Hollansburg, O.

12-3-80

Ralph Cappock

*If additional space is needed to complete well log, use next consecutive numbered form.