

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

508251

COUNTY Franklin TOWNSHIP Franklin SECTION OF TOWNSHIP 1
OWNER Lawrence H. Ward ADDRESS 10177 Stott Rd. New Carlisle, Ohio
LOCATION OF PROPERTY 1st house E of R# 735 1/4 mile on Stott Rd.

BAILING OR PUMPING TEST
(specify one by circling)

(specify one by circling)

Test rate 20 gpm Duration of test 2 hrs
Drawdown 30 ft Date _____
Static level (depth to water) 22 ft. ft
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Ray Hecker

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

A hand-drawn map showing a road intersection. A vertical road is labeled "SR" on the west side and "41" on the east side. A horizontal road is labeled "STOTT RD." at the top. A well is marked with a square symbol and the word "WELL" on the east side of the vertical road. The cardinal directions N, S, E, and W are indicated. A distance of "230" is marked on the south side of the vertical road.

ADDRESS

SIGNED

*If additional space is needed to complete well log, use next consecutive numbered form.