

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

509856

COUNTY Portage TOWNSHIP Deerfield SECTION OF TOWNSHIP _____
OWNER Raymond Basentini ADDRESS P.O. Box 165, Deerfield, Ohio 44411
LOCATION OF PROPERTY 1/4 mile north on Rt. #225 from Deerfield Circle

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 8" / 5" Length of casing 59 ft. / 220 ft.
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

Test rate 15 gpm Duration of test 24 hrs
Drawdown 25 ft Date 12-16-78
Static level (depth to water) 50 ft. ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by J. H. Kiser

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

<u>Clay</u>	0 ft	8 ft
<u>Glaucon Till</u>	8	54
<u>Shale & shells</u>	54	93
<u>Sandrock</u>	93	250

water at 245 ft.

