

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

509860

COUNTY Portage TOWNSHIP Randolph SECTION OF TOWNSHIP 44272
OWNER Edward J. Polack ADDRESS 3490 Sanford Rd. Portage, Ohio
LOCATION OF PROPERTY 4482 Alexander Rd. Portage, Ohio

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 6" ~~4"~~ Length of casing 24 ft Test rate 20 gpm Duration of test 24 hrs
Type of screen _____ Length of screen _____ Drawdown 10 ft Date 9-24-79
Type of pump _____ Static level (depth to water) 15 ft
Capacity of pump _____ Quality (clear, cloudy, taste, odor) clear
Depth of pump setting _____ Pump installed by _____
Date of completion _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay


From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

<u>Clay</u>	0 ft	6 ft
<u>Gravel Fill</u>	6	23
<u>Sandrock</u>	23	71

Water at 67 ft.



DRILLING FIRM Kisner Drilling Company

ADDRESS EZRA O. KISNER

540 New York Ave.

Sebring Ohio, 44872

DATE 10-8-79

SIGNED E.O. Kisner

* If additional log is needed, use next consecutive numbered form.

194