

WELL LOG AND DRILLING REPORT

C
ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

511559

562

COUNTY LICK ^{Franklin} TOWNSHIP LICK ^{Jefferson} SECTION OF TOWNSHIP _____
OWNER Bruce Johnson ADDRESS #2762 New Albany Hwy Rd.
LOCATION OF PROPERTY 3mi North of Havens Co Rd (on) New Albany Hwy Rd.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 Length of casing 136' 6" Test rate 5 gpm Duration of test 3 hrs
Type of screen — Length of screen — Drawdown 0 ft Date Sept 19, 1977
Type of pump Reel Jackbit Static level (depth to water) 80 ft
Capacity of pump 20 gpm Quality (clear, cloudy, taste, odor) clear
Depth of pump setting 135'
Date of completion Sept 8 1977 Pump installed by Dan Keaton

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

yellow clay.	0 ft	12 ft
yellow clay gravel mid	12	25
sand gravel conglomerate	25	47
gray clay sand mix	47	95
gray water sand	95	130
black clay.	130	133
gray shale.	133	138
black shale.	138	143
(Sunbury type)		
↓ Drill Ref.		

N
Rouville Rd.
64-8
22 mi. S of Clark
Slate Rd. E
e side
S
New Albany Hwy Rd.
Havens Co Rd.
1005
138
867

DRILLING FIRM Keaton Drilling

DATE Sept. 19, 1978

ADDRESS 3406 Chautau Rd. Columbus Ohio

SIGNED D. Keaton

289

*If additional space is needed to complete well log, use next consecutive numbered form.

2762 Reynoldsburg - New Albany Rd