

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

Nº 139600

County LUCAS Township SYLVANIA Section of Township or Lot Number _____
Owner ROBERT SAAM Address INDIAN RIDGE
Location of property FROM ALEXIS NORTH ON FLANDERS TO INDIAN RIDGE.
EAST ON INDIAN RIDGE 5th HOUSE ON NORTH SIDE

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 71
Type of screen _____ Length of screen _____
Type of pump SUBMERSIBLE
Capacity of pump 1/2
Depth of pump setting 60

PUMPING TEST


Pumping rate 12 G.P.M. Duration of test 3 hrs.
Drawdown 4 ft. Date 10-29-56
Developed capacity _____
Static level—depth to water 47 ft.
Pump installed by US

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>SAND</u>	<u>0 Feet</u>	<u>36 Ft.</u>
<u>CLAY</u>	<u>36</u>	<u>71</u>
<u>SANDSTONE</u>	<u>71</u>	<u>73</u>
<u>WATER</u>	<u>73</u>	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Fred Bull & Son
Address 4924 Alexis Rd

Date 10-30-56
Signed Fred L Bull