

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

521790

COUNTY Huron TOWNSHIP Greenwich SECTION OF TOWNSHIP _____
OWNER James Gallagher ADDRESS 1528 Larchmont, Lakewood, Ohio 44107
LOCATION OF PROPERTY On county Rd. 79, 1/4 mi. East of Rt. 250.

CONSTRUCTION DETAILS

Casing diameter 1.5" Length of casing 31'-8"
Type of screen None Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

(Specify one by circling)


Test rate 0 gpm Duration of test _____ hrs
Drawdown _____ ft Date Oct. 18, 1979
Static level (depth to water) _____ ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Brown Clay</u>	0 ft	16 ft
<u>Blue Clay</u>	16	28
<u>Black shale</u>	28	44
<u>Gray shale</u>	44	100

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM Roerig Drilling
ADDRESS New London, Ohio

DATE 12-29-1979
SIGNED Robert Roerig

*If additional space is needed to complete well log, use next consecutive numbered form.