

WELL LOG AND DRILLING REPORT

ORIGINAL

+88

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

521869

COUNTY Miami TOWNSHIP Newton SECTION OF TOWNSHIP 33-3
OWNER Harold Flora ADDRESS 6070 RT 41 Croydon
LOCATION OF PROPERTY on Rt 41 2 mi E Croydon S side

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 5/8 Length of casing 28
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

Test rate _____ gpm Duration of test _____ hrs
Drawdown _____ ft Date _____
Static level (depth to water) 2 ft ft
Quality (clear, cloudy, taste, odor) Boulders off
30 B.P.M. at 20 ft
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

sandy clay
limestone

0 ft

26 ft

26

70

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

Croydon

1 spring

W

E

Rt 41

10-Well

S

RECEIVED

NOV 03 1979

HEALTH DEPARTMENT
TROY, OHIO

DRILLING FIRM

D. J. High
192 R. Mains

DATE

10-30-79

SIGNED

D. J. High

*If additional space is needed to complete well log, use next consecutive numbered form.

26