WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER NECESSARY - SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

526427

COUNTY Trumbull TOWNSHIP ~~Leetonia~~ Warren SECTION OF TOWNSHIP

OWNER David Bianco ADDRESS 3730 Meadow Brook Dr. Leetonia

LOCATION OF PROPERTY

CONSTRUCTION DETAILS

Casing diameter 3 5/8 Length of casing 26

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 10 gpm Duration of test 2 hrs

Drawdown 20 ft Date 5/3/78

Static level (depth to water) ft

Quality (clear, cloudy, taste, odor)

Pump installed by

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Sand + Clay	0 ft	13 ft
Shale	13	50
~~Brown~~ Berea	50	90

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.