

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

527906

COUNTY WASHINGTON TOWNSHIP DUNHAM SECTION OF TOWNSHIP 30

OWNER BILL W. RIDDLE ADDRESS RT 11, DUNHAM

LOCATION OF PROPERTY NEAR INTERSECTION OF TWP 51 AND TWP 23

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 6" Length of casing 15

Test rate 14 gpm Duration of test 2 hrs

Type of screen _____ Length of screen _____

Drawdown 115 ft Date 7-2-60

Type of pump _____

Static level (depth to water) 16 ft

Capacity of pump _____

Quality (clear, cloudy, taste, odor) GOOD

Depth of pump setting _____

Date of completion 7-2-60

Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

CLAY

0 ft

15 ft

SANDSTONE

15

34

SHALE

34

125

WATER AT 18'

W

N

E

TWP 51

TWP 51

← 0.05 →

L.W. 11.6