

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

528636

COUNTY Preble TOWNSHIP Dixon SECTION OF TOWNSHIP 14

OWNER Carlos Wiles ADDRESS R#3 Eaton Ohio

LOCATION OF PROPERTY South side of Concord Rd. 1 mile east of Wyatt Rd.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 6" Length of casing 39'

Test rate 14 gpm Duration of test 2 hrs

Type of screen - Length of screen -

Drawdown 14 ft Date May 18 1980

Type of pump -

Static level (depth to water) 10 ft

Capacity of pump -

Quality (clear, cloudy, taste, odor) Clear

Depth of pump setting -

Date of completion May 18 1980

Pump installed by -

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

0 ft

ft

yellow clay
sand

15

15 20

Blue clay

20 27

Hard Pan

27 32

sand


32 38

Gravel

38 39

Locate in reference to numbered
state highways, street intersections, county roads, etc.

6112 N
Concord Rd



W

E

S