

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

528641

206

COUNTY Preble TOWNSHIP MONROE SECTION OF TOWNSHIP 29
OWNER C. H. EASTERLING ADDRESS RT # 40 ELDORADO, OHIO
LOCATION OF PROPERTY S. Side of RT 40 2 mi. EAST of 726

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 48'
Type of screen NONE Length of screen —
Type of pump SUBMERSIBLE
Capacity of pump 1/3 HP
Depth of pump setting 44'
Date of completion 12-30-80

BAILING OR PUMPING TEST

(specify one by circling)


Test rate 14 gpm Duration of test 2 hrs
Drawdown 6 ft Date 12-30-80
Static level (depth to water) 12' ft
Quality (clear, cloudy, taste, odor)
Pump installed by OWNER

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>SOIL</u>	<u>0 ft</u>	<u>2 ft</u>
<u>CLAY</u>	<u>2</u>	<u>46</u>
<u>WATER GRAVEL</u>	<u>46</u>	<u>48</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM Paxtons Well Drilling DATE 12-30-80
ADDRESS 3024 River Dr Greenville, OHIO SIGNED Harold C. Berman

*If additional space is needed to complete well log, use next consecutive numbered form.