

County Permit No.

WELL LOG AND DRILLING REPORT

ORIGINAL

56 ✓


529187

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBINGState of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224COUNTY Hancock TOWNSHIP Amanda SECTION OF TOWNSHIP # 9
OWNER Nate Hendues ADDRESS Vanlue
LOCATION OF PROPERTY West end of Vanlue in town**CONSTRUCTION DETAILS**Casing diameter 5 5/8 Iron pipe Length of casing 21
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion Aug 22 77**BAILING OR PUMPING TEST**

(specify one by circling)

Test rate 10 gpm Duration of test _____ hrs
Drawdown _____ ft Date _____
Static level (depth to water) _____ ft
Quality (clear), cloudy, taste, odor) _____
Pump installed by _____**WELL LOG***

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Clay</u>	0 ft	20 ft
<u>sand</u>	20	21
<u>limestone</u>	21	34
<u>Water at 30</u>		

SKETCH SHOWING LOCATIONLocate in reference to numbered
state highways, street intersections, county roads, etc.

DRILLING FIRM

Carl Barger

DATE

Sep 18-78

ADDRESS

RR1 Vanlue

SIGNED

Carl Barger

*If additional space is needed to complete well log, use next consecutive numbered form.