

County Permit No.

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

DEPARTMENT OF NATURAL RESOURCES

531358

Division of Water

Fountain Square

Columbus, Ohio 43224

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBINGCOUNTY HURON TOWNSHIP TOWNSEND SECTION OF TOWNSHIP _____OWNER HOWARD RIEDY ADDRESS WELLS RDLOCATION OF PROPERTY WELLS RD 1/2 MILE E. OF US#61

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 6" OD Length of casing 17' Test rate 40 gpm Duration of test 2 hrs

Type of screen — Length of screen — Drawdown 3 ft Date 11-5-80

Type of pump — Static level (depth to water) 3' ft

Capacity of pump — Quality (clear, cloudy, taste, odor) CLEAR, NO ODOR

Depth of pump setting 50'

Date of completion 11-5-80 Pump installed by —

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

<u>SANDY CLAY</u>	<u>0 ft</u>	<u>8 ft</u>
<u>YELLOW SANDSTONE</u>	<u>8</u>	<u>15</u>
<u>SANDSTONE (GREY)</u>	<u>15</u>	<u>60</u>

WATER AT
23 & 55

N

W

E

