

83-116

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

533115

COUNTY OTTAWA TOWNSHIP DANBURY SECTION OF TOWNSHIP Lot. #1 - Sec. 1
OWNER MICHAEL J. GRESH JR. ADDRESS 9415-E. BAYSHORE RD MARBLEHEAD OH 43440
LOCATION OF PROPERTY 8850 HARTSHORN RD. MARBLEHEAD, OHIO, 43440

CONSTRUCTION DETAILS

Casing diameter 6 inch Length of casing 23 ft
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 11-30-83

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 15 gpm Duration of test 24 hrs
Drawdown _____ ft Date _____
Static level (depth to water) 10 FT. ft
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by OWNER

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

CLAY

0 ft

12 ft

LIME-STONE

12'

81'

WATER-AT-45-FT.

23-FT. GALVANIZED

6-INCH CASING-WITH

FLARED-ADAPTOR

ON END

CEMENTED-IN-

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.