

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

533605

COUNTY Butler TOWNSHIP Hanover SECTION OF TOWNSHIP _____
OWNER Edward Ziepfel ADDRESS Stalhaber Rd.
LOCATION OF PROPERTY Stahlheber Rd ←

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 22
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 4 1/2 gpm Duration of test 1 hrs
Drawdown all the way ft Date 3/31/81
Static level (depth to water) 18 ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by Others

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Topsoil	0 ft	5 ft
Clay	5	7
Hardpan - Rocky	7	9
Blue Clay-Soft rock	9	18
Limestone, Rocky	18	38

water at 18°

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

A hand-drawn map showing the intersection of Stalhaber Rd. and Rt. 27. The map is oriented with North (N) at the top, South (S) at the bottom, East (E) to the right, and West (W) to the left. A vertical line represents Rt. 27, and a horizontal line represents Stalhaber Rd. The intersection is marked with an 'X'. A north arrow is located in the top right corner of the map.

DRILLING FIRM Wm. Readway
ADDRESS Hamilton

DATE 4/2/81

SIGNED _____

*If additional space is needed to complete well log, use next consecutive numbered form.

28