

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

533680

COUNTY Marion TOWNSHIP Big Island SECTION OF TOWNSHIP _____
OWNER Larry Limestone ADDRESS 2181 Green Camp River Rd
LOCATION OF PROPERTY St. R. 37

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(specify one by circling)

Casing diameter 5" Length of casing 44' Test rate 100 gpm Duration of test 1 hrs
Type of screen — Length of screen — Drawdown — ft Date MAY 13, 1978
Type of pump _____ Static level (depth to water) 12 ft
Capacity of pump _____ Quality (clear, cloudy, taste, odor) Clear
Depth of pump setting _____ Pump installed by _____
Date of completion May 13, 1978

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Clay

0 ft

40 ft

LIMESTONE

40

80

Water at

80

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

#37 WELL

W

#203

E

S

DRILLING FIRM CRAY DRILLING
ADDRESS 501 SUSAN CIRCLE
MARION, OHIO 43302

DATE 7/24/78
SIGNED Lowell Cray