

WELL LOG AND DRILLING REPORT

County Permit No.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

540428

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

Division of Water
Fountain Square
Columbus, Ohio 43224

COUNTY Meigs TOWNSHIP Chesler SECTION OF TOWNSHIP N.W.
OWNER Harold Schultz ADDRESS 11811 E. Hill Dr.
LOCATION OF PROPERTY 3 mi. off Wilsonville Rd on E. Hill Dr

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 6" OD Length of casing 72
Type of screen None Length of screen 5 ft
Type of pump Sub
Capacity of pump 12 GPM Depth of pump setting 100'
Date of completion _____
Pump installed by Robert W. Huling

Test rate 21 gpm Drawdown 10 ft Date 8-20-83
Static level (depth to water) 70 ft
Quality (clear, cloudy, taste, odor) Clear
Duration of test 2 hrs

SKETCH SHOWING LOCATION

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay

From To

30'	0 ft	Clay - sand
60'	30'	Sandy gravel
65'	60'	Shale
78'	65'	Sandstone
118'	78'	

Locate in reference to numbered state highways, street intersections, county roads, etc.

S	
Wilsonville Rd	
East Hill Dr	
N	
Mudbury Rd	
E	
Well 50' x 50' Home	

DRILLING FIRM

ADDRESS

SIGNED

DATE

8-23-83

W.M. Huling Drilling Co.
12186 Cheltenham Rd.
Chesler, OH

If additional space is needed to complete well log, use next consecutive numbered form.