

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

541427

20a
L

COUNTY PREBLE TOWNSHIP MONROE SECTION OF TOWNSHIP ~~32~~ 31
OWNER DON HALL ADDRESS R#1 Eldorado, O
LOCATION OF PROPERTY St. Rt. 127 to St. Rt. 40 61 to 726 3rd place on S.

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 70

Type of screen _____ Length of screen _____

Type of pump 50 KWO-9CRBC

Capacity of pump 10 G.P.M

Depth of pump setting 30'

Date of completion 6/20/80

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 20 gpm Duration of test 1 hrs

Drawdown 1.5 ft Date 6/20/80

Static level (depth to water) 21 ft

Quality (clear, cloudy, taste, odor) _____

Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

0 ft | 12 ft

12 | 17

17	56
----	----

56	64
----	----

64 | 70

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

W

E

S

DRILLING FIRM**ADDRESS**

DATE _____

SIGNED