

County Permit No.

WELL LOG AND DRILLING REPORT

ORIGINAL

6667
Pump 1288
 NO CARBON PAPER
 NECESSARY—
 SELF-TRANSCRIBING

State of Ohio
 DEPARTMENT OF NATURAL RESOURCES
 Division of Water
 Fountain Square
 Columbus, Ohio 43224

564204

COUNTY Wood TOWNSHIP Perry Twp. SECTION OF TOWNSHIP 14
 OWNER Gary Stranberg ADDRESS 2399 Engleville Rd.
 LOCATION OF PROPERTY 2 miles West of St Rt 23 on Engleville Rd.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(specify one by circling)

Casing diameter 5 7/8 Length of casing 21-4
 Type of screen _____ Length of screen _____
 Type of pump _____
 Capacity of pump _____
 Depth of pump setting _____
 Date of completion Sept. 19, 1958

Test rate 20 gpm Duration of test 2 hrs
 Drawdown 2 ft Date Sept 19, 1958
 Static level (depth to water) 10' ft
 Quality (clear, cloudy, taste, odor) clear
 Pump installed by owner

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

0 ft

1 ft

197Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

W

E

X
 Engleville Rd

St Rt 23

C to P.R.