

County Permit No. \_\_\_\_\_

**WELL LOG AND DRILLING REPORT**

ORIGINAL

NO CARBON PAPER  
NECESSARY -  
SELF-TRANSCRIBINGState of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
Fountain Square  
Columbus, Ohio 43224

564603

COUNTY Fairfield TOWNSHIP Bloom SECTION OF TOWNSHIP \_\_\_\_\_  
OWNER Alfred Bartlett ADDRESS 3485 Kaufman Road, Carroll Ohio  
LOCATION OF PROPERTY Same as above**CONSTRUCTION DETAILS****BAILING OR PUMPING TEST**  
(specify one by circling)Casing diameter 5 1/2 in Length of casing 60' 10"Test rate 15 gpm Duration of test \_\_\_\_\_ hrs

Type of screen \_\_\_\_\_ Length of screen \_\_\_\_\_

Drawdown 1' 4" ft Date \_\_\_\_\_Type of pump F.W.Static level (depth to water) 35 ft ftCapacity of pump 15 G.P.M.Quality (clear, cloudy, taste, odor) ClearDepth of pump setting 40 ftDate of completion 12-15-79

Pump installed by \_\_\_\_\_


**WELL LOG\*****SKETCH SHOWING LOCATION**Formations: sandstone, shale,  
limestone, gravel, clay

From

To

0 ft

ft

Brown sandy Clay 0 1815 ftBrown soft sandy Clay 18 46Soft Gray Clay 46 55Gray sand & gravel 55 60Locate in reference to numbered  
state highways, street intersections, county roads, etc.DRILLING FIRM Stewart Steel DrillingDATE 12-17-79ADDRESS 3650 Logan Road,  
Lancaster, OhioSIGNED Charles Corbly

\*If additional space is needed to complete well log, use next consecutive numbered form.