

WELL LOG AND DRILLING REPORT

564605

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

#48

COUNTY Fairfield TOWNSHIP Bloom SECTION OF TOWNSHIP _____
OWNER Robert Larbig ADDRESS 7675 Obeklin Court, Lancaster, Pa. 17606
LOCATION OF PROPERTY College View Estates - Lot #48

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 10 gpm Duration of test 24 hrs

Drawdown 2 ft Date 3/30

Type of pump _____ Static level (depth to water) 80 ft

Capacity of pump _____ Quality (clear, cloudy, taste, odor) Clear

Depth of pump setting _____

Date of completion 3/31/80 Pump installed by Gillis Stewart

SKETCH SHOWING LOCATION

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Class	0 ft	20 ft
-------	------	-------

Blue Clay	20	30
-----------	----	----

Red Sand	30	100
----------	----	-----

yellow sand	100	150
-------------	-----	-----

Course Gravel	150	170
---------------	-----	-----

DRILLING FIRM. Stewart Shell Drilling

DATE 4-1-80

ADDRESS 3650 Logan Road

SIGNED

Laureate. Ohio 43130

*If additional space is needed to complete well log, use next consecutive numbered form.