

WELL LOG AND DRILLING REPORT

He ✓

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

564606

COUNTY Licking TOWNSHIP Simma SECTION OF TOWNSHIP _____
OWNER Cliff Smith ADDRESS 281 Pearl Lane, Pickerington Ohio
LOCATION OF PROPERTY Taylor Road

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 12 gpm Duration of test 3 days

Drawdown _____ ft Date _____

Static level (depth to water) 100 ft

Quality (clear, cloudy, taste, odor) _____

Pump installed by Phillip Stewart

Date of completion. 5/16/80

Pump installed by Phillip Stewart

SKETCH SHOWING LOCATION

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Colony	0 ft	1.5 ft
--------	------	--------

Blue Clay	15	120
-----------	----	-----

Red clay	120	140
----------	-----	-----

Sand	140	150
------	-----	-----

Travel	150	165
--------	-----	-----

[illegible][illegible]

[illegible]

--	--	--	--

[illegible]

--	--	--

--	--	--

[illegible]

--	--	--

--	--	--

N

S

Hand-drawn map showing a road intersection. The vertical road is labeled "Hayden Road". The horizontal road is labeled "RT 16". The intersection is marked with a crosshair. The letters "W" and "E" are at the ends of the horizontal road, and "N" and "S" are at the ends of the vertical road.

DRILLING FIRM Stewart Shell Drilling DATE 5/29/80

ADDRESS 3650 Logan Road. SIGNED *John D. Williams*

Lancaster, Ohio 43130

SIGNED John C. Campbell

*If additional space is needed to complete well log, use next consecutive numbered form.

170