

WELL LOG AND DRILLING REPORT

NO. 56758

Location of property 1 mi S. $\frac{1}{2}$ mi E of Graytown

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Date of completion _____ Pump installed by _____

WELL LOG		SKETCH SHOWING LOCATION	
Formation	From	To	
clay ls.	0	48 64	N. W. E. S.

Address _____ Copied by RS

51