

LOCATED

WELL LOG AND DRILLING REPORT

NO. 71
56772

County Ottawa Township Benton Section of Township _____
Owner Harvey Frederick Address Troubridge 0
Location of property _____

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 5 5/8 Length of casing 54 Pumping rate _____ G.P.M.
Type of screen _____ Length of screen _____ Duration of test _____ hrs.
Type of pump _____ Drawdown _____ ft. Date 7-20-51
Capacity of pump _____ Developed capacity _____
Depth of pump setting _____ Static level - depth to water 25 ft.
Date of completion _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formation

From

To

N.

clay
ls.

0

49

80

W.

E.

S.

Drilling Firm R.S. Rudes.

Date 2-26-60

Address _____

Copied by ES

71