

5778

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

575469

COUNTY Shawnee TOWNSHIP Munson SECTION OF TOWNSHIP —
OWNER Tom Janes ADDRESS 13039 Millstone Dr.
LOCATION OF PROPERTY 1 mile west of Bass Lake Rd on Millstone Dr

CONSTRUCTION DETAILS

Casing diameter 5 5/8" Length of casing 95 ft
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —
Date of completion —

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 12 gpm Duration of test 24 hrs
Drawdown Complete ft Date 11-25-80
Static level (depth to water) — ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by —

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay


From

To

Clay	0 ft	21 ft
Clay + sand	21	40
Clay - sand - gravel	40	72
sand	72	95
sandstone	95	110
shale	110	195

Water at 108 ft

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

DRILLING FIRM

J. B. Bruce

ADDRESS

Rt 1, Sunbury, OH

DATE

12-4-80

SIGNED

J. B. Bruce