

5778

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

575470

COUNTY Deane TOWNSHIP Munson SECTION OF TOWNSHIP _____
OWNER Tom James ADDRESS 13039 Millstone Dr.
LOCATION OF PROPERTY 1 mile west of Bass Lake Rd on Millstone Dr.

CONSTRUCTION DETAILS

Casing diameter 5 5/8" Length of casing 96 ft
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 24 gpm Duration of test 24 hrs
Drawdown 32 ft Date 12-1-80
Static level (depth to water) 28 ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Clay

0 ft

24 ft

Clay + sand

24

43

Clay - sand - gravel

43

75

Sand

75

96


Sandstone

96

112

Water at 110 ft

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

DRILLING FIRM

J. B. Bruce

DATE

12-4-80

ADDRESS

R. Huntsburg, OH

SIGNED

J. B. Bruce