

County Permit No.

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

575476

COUNTY Greene TOWNSHIP Middlefield SECTION OF TOWNSHIP 1
OWNER Robert Troyer ADDRESS 14131 Rt. 608 Middlefield
LOCATION OF PROPERTY 1 1/2 miles north of Middlefield on Rt. 608

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(specify one by circling)

Casing diameter 5 5/8" Length of casing 171 ft Test rate 12 gpm Duration of test 24 hrs
Type of screen Length of screen Drawdown 6.5 ft Date 6-3-81
Type of pump Static level (depth to water) 74 ft
Capacity of pump Quality (clear, cloudy, taste, odor) clear
Depth of pump setting
Date of completion Pump installed by

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay


From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Clay	0 ft	58 ft
Clay + sand	58	86
sand	86	164
sand & clay	164	171
shale	171	190
sandstone	190	198

Water at 195 ft



DRILLING FIRM

DATE

ADDRESS

SIGNED

*If additional space is needed to complete well log, use next consecutive numbered form.