

WELL LOG AND DRILLING REPORT

15.0

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

591341

COUNTY DARKE TOWNSHIP MONROE SECTION OF TOWNSHIP 13
OWNER RICK CHAPP ADDRESS 1861 ST. RT. 49 - ACCANUM C.
LOCATION OF PROPERTY NE CORNER OF ST. RT. 49 & GE. THYSBURG - T. 136.400 Rd.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 4 1/4 Length of casing 90'

Test rate 3 gpm Duration of test 5 hrs

Type of screen _____ Length of screen _____

Drawdown 102 ft Date 12/28/82

Type of pump _____

Static level (depth to water) 16 ft

Capacity of pump _____

Quality (clear, cloudy, taste, odor) P. L. E. A. K.

Depth of pump setting _____

Date of completion _____

Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

CLAY

0 ft

8 ft

HARD PAN

8

27

W. LIMESTONE

87

127

SHALE

127

142

W

N

E

S

DRILLING FIRM

DATE

ADDRESS

SIGNED

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

50