

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

591653

COUNTY Lucas TOWNSHIP Sylvania SECTION OF TOWNSHIP 12
OWNER Richard Downing ADDRESS 4833 Crestridge
LOCATION OF PROPERTY 3/8 mile south of 184 on crestridge

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 71

Type of screen NA Length of screen

Type of pump Sub

Capacity of pump 10 GPM

Depth of pump setting 60

Date of completion 4-10-81

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 20 gpm Duration of test 4 hrs

Drawdown 10 ft Date 4-9-81

Static level (depth to water) 32 ft

Quality (clear, cloudy, taste, odor) clear

Pump installed by Dr. Mer

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

5 dnd	0 ft	32 ft
-------	------	-------

Clay	32	52
------	----	----

Clay & gravel	52	68
---------------	----	----

Limestone	68	72
-----------	----	----

water at 71		
-------------	--	--

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

DRILLING FIRM Aicictas Ent Inc

ADDRESS 4733 Vineland Terrace, 6

DATE 5-10-81

SIGNED John L. Bell (pres)

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 137