

WELL LOG AND DRILLING REPORT

EA ✓

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

591958

COUNTY VINTON TOWNSHIP SWAN SECTION OF TOWNSHIP 16 (15)
OWNER MR. ELDON ANDREWS ADDRESS RT. C CREOLA OHIO
LOCATION OF PROPERTY 3 miles N. of Creola Ohio on Rt 93

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 83
Type of screen NONE Length of screen NONE
Type of pump DEEP-WELL - SUB
Capacity of pump 2400 PH 2
Depth of pump setting 156 2
Date of completion 221 Sept 1981

BAILING OR PUMPING TEST

(specify one by circling)


Test rate 15 gpm Duration of test 2 hrs
Drawdown 140 ft Date 5 Sept 1981
Static level (depth to water) 40 ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by 2

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Surface</u>	0 ft	4 ft
<u>Creek sand & gravel</u>	4	18
<u>Blue sand rock & shale</u>	18	61
<u>Lime</u>	61	69
<u>Penn Limer shale</u>		
<u>& sand rock</u>	69	83
<u>Penn Lim shale</u>		
<u>& sand rock</u>	83	133
<u>INJUN SAND</u>	133	166

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM KESSLER DR
ADDRESS RT 3 WELLSVILLE

DATE 8 Sept 81
SIGNED AKessler

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

39