

WELL LOG AND DRILLING REPORT

GS ☒

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

591959

COUNTY VINTON TOWNSHIP ELK SECTION OF TOWNSHIP 33
OWNER MR. GARYIN SALTS ADDRESS DUNDAS OHIO
LOCATION OF PROPERTY 3/4 mile south of McArthur Ch. rd. 93

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 115
Type of screen NONE Length of screen NONE
Type of pump DEEP-WELL
Capacity of pump 5 GPM
Depth of pump setting 180 FT
Date of completion 19 Sept. 1981

BAILING OR PUMPING TEST (specify one by circling)


Test rate 5 gpm Duration of test 2 hrs
Drawdown 180 ft Date 18 Sept
Static level (depth to water) 60 ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by Driller (Gary Salts)

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Surface</u>	0 ft	3 ft
<u>Sandy Clay</u>	3	8
<u>Creek & gravel</u>		
<u>Sand</u>	8	18
<u>Gray sand rock</u>	18	35
<u>Blue shale</u>	35	70
<u>Coal B. fossil</u>	70	71
<u>Blue shale</u>	71	103
<u>Penon line</u>	103	136
<u>Pinkish shale</u>	136	139
<u>Penon line</u>	139	181
<u>Jefferson Sand</u>	181	200

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM Kessler Drilling
ADDRESS P.O. Box 3 McArthur Ch.

DATE 23 Sept. 81
SIGNED Kessler

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

72