

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

593604

COUNTY Shelby TOWNSHIP Danvers SECTION OF TOWNSHIP _____
OWNER Arrie Smith ADDRESS 14366 H.D. 274 Bathys, OH.
LOCATION OF PROPERTY same

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)

Casing diameter <u>5 1/2 (600) galv.</u> Length of casing <u>101</u>	Test rate <u>10</u> gpm Duration of test <u>3</u> hrs
Type of screen _____ Length of screen _____	Drawdown <u>4</u> ft Date <u>Nov. 2, 1981</u>
Type of pump _____	Static level (depth to water) <u>35</u> ft
Capacity of pump _____	Quality (clear, cloudy, taste, odor) <u>clear</u>
Depth of pump setting _____	Pump installed by _____
Date of completion <u>Nov. 2, 1981</u>	

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay


From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Topsoil	0 ft	4	ft
Sandy clay	4	52	
Br. sandy clay (dirty)	52	58	
Br. sandy clay	58	80	
Br. sandy clay (dirty)	80	89	
Hard pan	89	92	
shale	92	98	
gravel	98	101	

T.D. 101



DRILLING FIRM Miami Well Services

DATE Nov. 3 1981