

# WELL LOG AND DRILLING REPORT

95

NO CARBON PAPER  
NECESSARY -  
SELF-TRANSCRIBING

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
Fountain Square  
Columbus, Ohio 43224

593605

COUNTY Miami TOWNSHIP Eastbury SECTION OF TOWNSHIP 30  
OWNER Harold + Pauline Hess <sup>16050 Highway 81</sup> ADDRESS Covington of 45318  
LOCATION OF PROPERTY 1985 N Rt 589, Cassstown, OH

## CONSTRUCTION DETAILS

## SAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 5 5/8 to galv. Length of casing 63 ft.  
Type of screen        Length of screen         
Type of pump         
Capacity of pump         
Depth of pump setting         
Date of completion Nov. 16, 1981

Test rate 10 gpm Duration of test 3 hr. hrs  
Drawdown 4 ft Date Nov. 16, 1981  
Static level (depth to water) 26 ft  
Quality (clear, cloudy, taste, odor) clear  
Pump installed by       

## WELL LOG\*

## SKETCH SHOWING LOCATION

Formations: sandstone, shale,  
limestone, gravel, clay

From

To

Locate in reference to numbered  
state highways, street intersections, county roads, etc.

Top soil

0 ft

5 ft

Gravel + clay

5

45

Hard pan

45

48

Clay

48

53

Sand

53

59

Gravel

59

63

T.D. 63 ft.

N

W

E

S

DRILLING FIRM

Miami Well Service

895 S Walnut Avenue  
Sidney, Ohio 45365

ADDRESS

DATE

Nov 17, 1981

SIGNED

William S. Zimmerman

\*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

94