

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

COUNTY Miami TOWNSHIP Spring Creek SECTION OF TOWNSHIP _____
OWNER Dave Lillie ADDRESS 1101 Sutter, Piqua, OH
LOCATION OF PROPERTY 9008 Piqua Lexington Rd. Piqua, OH

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(Specify one by circling)

Specify one by circling:

Casing diameter 5 5/8" ID Length of casing 39

Test rate 10 gpm Duration of test 2 hrs

Type of screen _____ Length of screen _____

Drawdown 3 ft Date June 1, 1982

Type of pump _____

Static level (depth to water) 14 ft

Capacity of pump _____

Quality (clear, cloudy, taste, odor) clear

Depth of pump setting _____

Date of completion June 1, 1982

Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION


Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

	0 ft	18 ft
Dry large gravel		
Sand	17	26
Hard pan	26	31
Sandy clay	31	34
Sand (some clay)	34	36
Gravel (water)	36	39
TD 39		



DRILLING FIRM Miami Well Service
635 S. Walnut Avenue
 ADDRESS Sidney, Ohio 45365

DATE June 2, 1982
SIGNED William H. Zimmerman

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224