



WELL LOG AND DRILLING REPORT

10NO. 5939

County Preble Township Mouroc Section of Township 26
Owner Fred Slenker Address Eaton, O
Location of property US 40 E. 127 US

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4 Length of casing 46 Pumping rate 6 G.P.M.
Type of screen _____ Length of screen C Duration of test 1/2 hrs.
Type of pump Electric Drawdown none ft. Date 10-48
Capacity of pump 350 Developed capacity _____
Depth of pump setting 44 Static level - depth to water 20' ft.
Date of completion _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formation
clay hardpan
lime rock

From

To

0

42

46

N.

W.

E.

S.

Drilling Firm Ozro WittersDate 10-2-59

Address _____

Copied by RS109