

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

594822

1239

COUNTY Franklin TOWNSHIP Pleasant SECTION OF TOWNSHIP _____
OWNER Daniel Francis ADDRESS 3960 Lukens Rd
LOCATION OF PROPERTY Darbydale, OH. 7090 Iris Drive

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 6" O.D. Length of casing 97'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

Test rate 18 gpm Duration of test 24 hrs
Drawdown 0 ft Date 8-22-83
Static level (depth to water) 7.5' ft
Quality (clear) cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

yellow clay	0 ft	20 ft
Sand + gravel	20'	50'
Blue hardpan	50'	97'
limestone	97'	
Depth of well		142'

Sketch showing location of well. The well is located at the intersection of W 71665 and Iris Drive. The well is located at the intersection of W 71665 and Iris Drive. The well is located at the intersection of W 71665 and Iris Drive.

DRILLING FIRM

ADDRESS

DATE

SIGNED

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

335