

WELL LOG AND DRILLING REPORT

cor

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

594828

833

COUNTY FRANKLIN TOWNSHIP PRAIRIE Pleasant SECTION OF TOWNSHIP _____

OWNER JAMES R. PENIBERTON ADDRESS _____

LOCATION OF PROPERTY 5269 NORTON RD.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 6" Length of casing 105'

Test rate 15 gpm Duration of test 12 hrs

Type of screen _____ Length of screen _____

Drawdown 15 ft Date 6-25-84

Type of pump _____

Static level (depth to water) 70 ft

Capacity of pump _____

Quality (clear) cloudy, taste, odor) _____

Depth of pump setting _____

Pump installed by _____

Date of completion _____

WELL LOG*

SKETCH SHOWING LOCATION


Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

<u>Clay</u>	0 ft	21 ft
<u>Brown sand</u>	21	64
<u>Hardpan</u>	64	90
<u>Sand</u>	90	95
<u>Red clay</u>	95	105
<u>Limestone @</u>	105	
<u>Depth of well</u>	128'	



DRILLING FIRM

DATE

ADDRESS

SIGNED

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

308