

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

596122

COUNTY DARKE TOWNSHIP BUTLER SECTION OF TOWNSHIP 36 ✓

OWNER EZRA DENLINGER ADDRESS RR#1 WEST MANCHESTER, O.

LOCATION OF PROPERTY SOUTH SIDE BYERS ROAD 1/2 MILE EAST OF STATE RTE 722
AND BYERS ROAD

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 5/8 Length of casing 70

Test rate 14 gpm Duration of test 12 hrs

Type of screen NONE Length of screen

Drawdown 9 ft Date JAN 28 - 1984

Type of pump SHALLOW WELL

Static level (depth to water) 6 ft

Capacity of pump

Quality (clear, cloudy, taste, odor) CLEAR

Depth of pump setting

NO TASTE OR ODOR

Date of completion

Pump installed by OWNER

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

CLAY

0 ft

17 ft

CLAY-SAND

17

25

CLAY

25

50

SAND-GRAVEL-CLAY

50

63

CLAY

63

69

SAND-GRAVEL

69

70

WATER AT 70 FT.

W

STATE

ROAD

RTE 722

BYERS RD

WELL

E

S

DRILLING FIRM CRIST WELL DRILLING SERVICE

DATE

1-31-84

ADDRESS 8501 CH-HOME BRADFORD RD

SIGNED

Ernest Crist

*If additional space is needed to complete well log, use next consecutive numbered form.

NO: 444

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

70