

WELL LOG AND DRILLING REPORT

Webster, no logs!
10a

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

596126 ✓

COUNTY DARKE TOWNSHIP WAYNE SECTION OF TOWNSHIP 31 ✓
OWNER LARRY SIMMONS ADDRESS 8852 SEIBT RD. BRADFORD, O
LOCATION OF PROPERTY NORTH SIDE SEIBT RD. ACROSS FROM CHURCH IN WEBSTER VILLAGE

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 5/8 Length of casing 40
Type of screen NONE Length of screen _____
Type of pump SHALLOW WELL
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

Test rate 11 gpm Duration of test 1 hrs
Drawdown 2 ft Date 9-13-84
Static level (depth to water) 16 ft
Quality (clear, cloudy, taste, odor) CLEAR
NO TASTE OR ODOR
Pump installed by OWNER

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

CLAY-GRAVEL
LIMESTONE

0 ft

39 ft

39

50

WATER AT

47-50

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

W

E



DRILLING FIRM CRIST WELLDILLING SERVICE

DATE SEPT 13 1984

