

WEL' LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

596461

COUNTY Licking TOWNSHIP Union SECTION OF TOWNSHIP _____
OWNER Linda Cordray ADDRESS Columbus, Ohio
LOCATION OF PROPERTY 5809 Lancaster Rd Granville, Ohio

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 39
Type of screen _____ Length of screen _____
Type of pump Subm
Capacity of pump 10 gal
Depth of pump setting 100
Date of completion Oct 15-81

BAILING OR PUMPING TEST (specify one by circling)


Test rate 24 gpm Duration of test 2 hrs
Drawdown 0 ft Date Oct 15-81
Static level (depth to water) 80 ft
Quality (clear) cloudy, taste, odor) _____
Pump installed by Robert Davis

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Clay</u>	0 ft	22 ft
<u>Brown Sand Stone</u>	22	95
<u>Gray Sandstone</u>	95	120

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM Robert Davis Well Drilling
ADDRESS 16857 Belmont Rd Millersport

DATE Dec 30-81
SIGNED Robert L. Davis

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

5809 SR 37

(40)
216