

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

596927

COUNTY Richland TOWNSHIP Jackson SECTION OF TOWNSHIP 23
OWNER Richard Hutt ADDRESS RD #4 Shelby O
LOCATION OF PROPERTY .25 mi South of Taylortown on Ply-Springmill Rd.

CONSTRUCTION DETAILS

Casing diameter 4 1/2 Length of casing 70
Type of screen None Length of screen _____
Type of pump Bale
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 12 gpm Duration of test 1 hrs
Drawdown 4 ft Date 9-12-85
Static level (depth to water) 40 ft
Quality (clear, cloudy, taste, odor) OK
Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Clay

0 ft

16 ft

Sand

16

30

Clay

30

49

Sand

49

51

Clay

51

66

Sand

66

67

Shale


67

73

Water @ 70'

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM Finnegan Well Drilling
ADDRESS RD #1 Shelby O

DATE 9-13-85
SIGNED D.R. Finnegan

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224