

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

596928

COUNTY Richland TOWNSHIP Sharon SECTION OF TOWNSHIP 24
OWNER Marty Hall ADDRESS RD # 2 Shelby, O
LOCATION OF PROPERTY 3 mi West of Vernon Junction on St Rt. 61

CONSTRUCTION DETAILS

Casing diameter 4 1/2 Length of casing 67
Type of screen None Length of screen _____
Type of pump Bolo
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (specify one by circling)

Test rate 4 gpm Duration of test 1 hrs
Drawdown - ft Date 9-26-85
Static level (depth to water) 30 ft
Quality (clear, cloudy, taste, odor) odor
Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay


From

To

Clay	0 ft	9 ft
Sand	9	10
Clay	10	36
Sand	36	39
Clay	39	45
Fine Sand	45	50
Clay	50	55
Sand	55	55 1/2
Clay	55 1/2	60
Black Shale	60	75
Water @ 67'		

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM Finnegan Well Drilling DATE 9-28-85
ADDRESS RD #1 Shelby O SIGNED D.R. Finnegan

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224