WELL-LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

NO CARBON PAPER NECESSARY – SELF-TRANSCRIBING

598351

COUNTY Wayne TOWNSHIP Milton SECTION OF TOWNSHIP 8

OWNER Floyd Fawcett ADDRESS 13658 Kaufman Ave

LOCATION OF PROPERTY Sterling Ohio

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 82

Type of screen 50# Length of screen 6'

Type of pump

Capacity of pump

Depth of pump setting

Date of completion Jan. 21 1980

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 20 gpm Duration of test 2 hrs

Drawdown 10 ft Date

Static level (depth to water) ft

Quality (clear, cloudy, taste, odor)

Pump installed by Owner

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Clay	0 ft	8 ft
Gravel	8	12
Blue Clay	12	76
Gravel	76	82

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM R. A. Hatfield + Son DATE Feb 3 1981

ADDRESS 9938 Cold Brook Rd SIGNED John Hatfield

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 1/4/5