

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

598352

COUNTY Wayne TOWNSHIP Milton SECTION OF TOWNSHIP 8, 9
OWNER Richard Farber ADDRESS 7111 Atlantic Ave
LOCATION OF PROPERTY Sterling Ohio

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 114
Type of screen 1/4 Pea Gravel Length of screen 20'
Type of pump Sub
Capacity of pump 20 GPM
Depth of pump setting 70'
Date of completion 4-11-81

BAILING OR PUMPING TEST

(specify one by circling)


Test rate 50 gpm Duration of test 2 hrs
Drawdown 30 ft Date 4-11-81
Static level (depth to water) 18' ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by OWNER

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Clay</u>	<u>0 ft</u>	<u>8 ft</u>
<u>Gravel</u>	<u>8</u>	<u>12</u>
<u>Blue Clay</u>	<u>12</u>	<u>85</u>
<u>Gravel</u>	<u>85</u>	<u>90</u>
<u>Blue Clay</u>	<u>90</u>	<u>92</u>
<u>Gravel</u>	<u>92</u>	<u>114</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM R. A. Hatfield & Son
ADDRESS 9938 Coal Bank Rd

DATE 4-13-81
SIGNED John Hatfield

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 ③A