

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

598353

COUNTY Wayne TOWNSHIP Milton SECTION OF TOWNSHIP 11
OWNER Jan Crumley ADDRESS 15205 Shoreline Rd. Sterling
LOCATION OF PROPERTY _____

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 25
Type of screen N/A Length of screen N/A
Type of pump _____
Capacity of pump 13 Hp
Depth of pump setting 50'
Date of completion Oct 1 1981

BAILING OR PUMPING TEST

(specify one by circling)


Test rate 10 gpm Duration of test 1 hrs
Drawdown 20' ft Date Oct 2, 1981
Static level (depth to water) 9' ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by Drillers

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Clay</u>	<u>0 ft</u>	<u>20 ft</u>
<u>Shale</u>	<u>20</u>	<u>80</u>
<u>Water At</u>	<u>45'</u>	<u>60'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM R. A. Hatfield & Son
ADDRESS 9938 Coal Bank Rd

DATE Oct 7, 1981
SIGNED John Hatfield

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 52